ACCIDENTS INVOLVING FLAMMABLE REFRIGERANTS Revised: 7 February 2002

Date Location/Description/Summary

12/23/2001 Madison, Wisconsin, USA: Oscar Mayer Foods Two men were moving a tank of ammonia in a loading dock when a line broke, spilling 50 gallons of ammonia.

Injuries/Damage: One person died from ammonia exposure and two others required hospital treatment. Of the two, one was in serious condition.

ŗ

Documentation: Associated Press news release and two newspaper accounts including the Chicago Tribune.

11/12/2001 Treviso, Italy: ELECTROLUX

An explosion of Isobutane, R-600a, took place at an ELECTROLX factory that manufacturers refrigerators that use R-600a as a refrigerant. The fire took place in an area used to assemble compressors for refrigerators. Flames blazed up in a 1-meter deep pit, in which welding is normally carried out. It is suspected that there was a leak of Isobutane used to charge the refrigerators and the refrigerant pooled in the welding pit until it was ignited.

Injuries/Damage: Eight persons suffered injures that required a hospital visit. Three were reportedly seriously burned. "The 3 most heavily injured female employees were affected by the shock wave and by the flames, which resulted from the explosion. The other 5 colleagues threw themselves immediately over the 3 women in order to extinguish the flames with their own bodies."

Documentation:

- CNN News article dated 12 November 2001
- 7/12/2001 New South Wales, Australia: University of New South Wales Dr. Maclaine-cross, a HC refrigerant researcher, was conducting a demonstration of the safety of HC refrigerants using his own vehicle. The demonstration resulted in an explosion, injuring Dr. Maclaine-cross and one other. Their injuries required medical treatment but not hospitalization.
- 7/5/1999 Adelaide, Australia: Café Grove, Village Shopping Center
 Fire incident involving a refrigeration unit containing a Calor Gas "Care"
 HC refrigerant blends (Propane and butane) during service. A refrigerant
 pipe ruptured during the recycling process. The escaping gas was

reportedly ignited when the service technician pulled the electrical lead out of a power point, causing an arc.

Injuries/Damage: Two were reportedly seriously burned - the service technician and café owner, both of them in the vicinity of the refrigeration equipment. A third worker in the café was unharmed. Half of the café was engulfed in flames.

Documentation:

- Newspaper article
- Fire Case Notes # 8 South Australian Metropolitan Fire Service.
- Hazard Alert No. 17, Workplace Services, Australian Department for Administrative and Information Services, September 1999. (http://www.eric.sa.gov.au/hazard_alerts/hazaler17.pdf)
- Official Report of Accident by Graham Stephens, Inspector, Occupational Health & Safety, Community Services Team, dated 18 January 2000.
- 1999/2000 Adelaide, Australia Fire and/or explosion in a refrigerator allegedly from a leaking aerosol container stored in the refrigerator. Investigated by Workplace Service in Adelaide.

Injuries/Damage: Not disclosed.

Documentation: None available as of 26 March 2000.

1999/2000 Texas, USA:

Alleged news report of an explosion from an ammonia system blowing out the wall of beer brewery in Texas.

Documentation: None available as of 26 January 2001

1999 Switzerland:

Fire incident during service of an indirect closed system heat pump. The condenser of an air-water heat pump was leaking. Due to the large pressure drop between heat pump and hydronic heat distribution systems, propane (R-290) was flowing into the hydronic system. After opening a bleeding valve of the circulation pump, unfortunately being illuminated with a lighter, propane ignited with a jet of flame.

Injuries: Fortunately no personal injuries resulted.

Documentation: Memo from Joel Crespin to Joint Working Group IEC SC61D/ISO TC86/SC1

Unknown Australia Alleged explosion of a propane cylinder in the cab of an HVAC&R service technician. Injuries: Unknown Documentation: None on hand at present. Unknown Sweden Alleged explosion involving a chiller or heat pump while being recharged with isobutane.

.

Documentation: None available

. *

.

÷